



SERVING THE CAROLINAS FOR 30 YEARS

**FOX FIRE VILLAGE POOL
14 FOX FIRE BLVD
JACKSON SPRINGS, NC 27281**

LESLIE FRUSCO

WE PERFORMED A LEAK TEST ON ALL POOL LINES AUGUST 18TH. ALL LINES PASSED BUT THE FLOOR RETURNS. THEY DID NOT HOLD PRESSURE. WE LOCATED THE BROKEN AREA. WE RETURNED ON OCTOBER 1ST & 2ND AND LOCATED THE LEAK WITHIN A 2FT AREA. WE PRESSURED TESTED LINES AGAIN AND HELD NO PRESSURE. WE REMOVED THE CONCRETE AND FOUND THE LEAK AT A T FITTING FOR ONE OF THE RETURNS. WE REMOVED THE T FITTING AND REPLACED WITH NEW SCHEDULE 40 FITTING. WE RESET THE LINE WITH NEW SCHEDULE 40 2 1/2 PIPE AND RETESTED THE LINES WITH 25LBS POUNDS OF PRESSURE AND IT HELD FOR 20 MINUTES. WE COVERED THINGS BACK UP WITH 4000PSI CONCRETE AND HYDRAULIC CEMENT TO WATERPROOF.

WE FOUND NO UNDERMINING OF ANY GRAVEL UNDER POOL SHELL. THE CURRENT SHOT-CRETE SHELL WAS IN VERY GOOD SHAPE.

IF YOU HAVE ANY FURTHER QUESTIONS PLEASE CONTACT OUR OFFICE.

BEST REGARDS

**STAN C. EAVES II
CEO
AQUA POOLS GROUP, LLC**